



STS-121 Flight Readiness Review

External Tank Project (ET-119)



June 16, 2006




STS-121

	Agenda	Presenter M. Quiggle, LM-ET/ 300
	Agenda	Date June 16, 2006 Page 2
Тор	<u>ic</u>	<u>Status</u>
ET-	119/STS-121 Processing / Certification Overview	To be presented
Res	olution of Anomalies from Previous Flight	To be presented
Con	figuration Inspection	No issues
Cha 4.1 4.2	inges Since Previous Flight Requirements Configuration	To be presented To be presented
4.3 4.4	Process Planned Work	No issues No issues
4.5	OMRSD	No issues
4.6	LCC	No issues
Sen	ior Management Review Nonconformance Items	No issues
Тес	hnical Assessments	No issues
STS	-121 Readiness Assessment	To be presented
Spe 8.1 8.2	cial Topics STS-121 Possible Outcomes STS-300 LON Readiness Assessment	To be presented



STS-121








2.0 Resolution of Anomalies from Previous Flight

- Presenter M. Quiggle, LM-ET/ 3000
- Six (6) External Tank In-Flight Anomalies (IFAs) documented
 - Fault Tree Investigation complete
 - Root cause testing complete
 - Most probable cause of IFAs identified
- IFA Investigation Teams (MSFC/NASA IFA Team and SSP HQ Tiger Team) identified recommendations for ET Project consideration
 - 83 total recommendations received
 - All mandatory items implemented
 - Items with potential scope impact forwarded to ET Project Configuration Control Board (CCB) for assessment



STS-114 IFA Fault Tree					
Team	Open	Closed	Total		
T-01, Flange	0	28	28		
T-02, Bipod	0	20	20		
T-03, PAL Ramp	0	30	30		
T-04, Ice/Frost	0	20	20		
T-05, Acreage	0	14	14		
T-06, Thrust Strut	0	69	69		
Total 0 181 181					

SPACE SHUTTLE PROGRAM

Shuttle Propulsion NASA Marshall Space Flight Center, Huntsville, AI



STS-121

2.0Resolution of Anomalies from
Previous Flight – Root Cause DeterminationPresenterM. Quiggle, LM-ET/ 3000DateJune 16, 2006Page 5

Thrust Strut Flange TPS Closeout (STS-114-T-06)


 <u>Most Probable Cause</u> <u>Scenario(s)</u>: Secondary impact or multiple subsurface voids resulting in observed foam loss

LH2 Tank Acreage, 2 locations (STS-114-T-05)

- <u>Xt 1160 Most Probable Cause</u> <u>Scenario:</u> Work induced damage or delta pressure void in adjacent repair
- <u>Xt 1851 Most Probable Cause</u> <u>Scenario:</u> Cryopumping divot event due to voids, cracks and/or delaminations

LH2 Ice/Frost Ramps (IFRs), 3 locations (STS-114-T-04)

- <u>Xt 1262 and 1841 Most Probable</u> <u>Cause Scenario</u>: Divoting due to an internal process-induced void and delta pressure
- <u>Xt 1525 Most Probable Cause</u> <u>Scenario:</u> Impact during ascent due to TPS, ice or other Shuttle element debris



Intertank/LH2 Tank Flange, 2 locations (STS-114-T-01)

• <u>Most Probable Cause Scenario:</u> Foam loss caused by voids in the close-out manual spray foam subjected to ascent thermal and pressure environments

Bipod Fitting Closeout (STS-114-T-02)

- <u>Most Probable Cause Scenario</u>: Divot caused by cryoingestion through and into cable
- LH2 PAL Ramp (STS-114-T-03)
- <u>Most Probable Cause Scenario</u> (combination of the following)
 - Cryopumping of outside air through leak path connecting to atmosphere
 - Defects(s) and or damage to initiate failure or driving force to peel foam from tank

SPACE SHUTTLE PROGRAM

Shuttle Propulsion NASA Marshall Space Flight Center, Huntsville, AI





Presenter **Resolution of Anomalies from** 2.0 M. Quiggle, LM-ET/ 3000 **Previous Flight – Mitigations for STS-121** Date June 16, 2006 Page 6

Thrust Strut Flange TPS Closeout


- Analysis indicates > expected or multiple voids required to result in STS-114 foam loss size / mass
- Dissected additional hardware to validate void distribution (used in PRA)
- Closeout redesign future implementation • (SSP assessment)

LH2 Tank Acreage

- Enhanced controls for tooling. documentation & personnel access
- Assessed effectiveness of damage detection, damage repair techniques and effects of crushed foam (used in PRA)
- Redesign to mitigate thermal induced ٠ delaminations under IFR for future implementation (SSP assessment)

LH2 Ice/Frost Ramps

- Assessed additional hardware to validate void distribution (used in PRA)
- Considered ET-120 dissection observations in design verification (wind tunnel, cryo/thermal vac tests)
- · Redesign to mitigate thermal induced delaminations under IFR for future implementation (SSP assessment)



Intertank/LH2 Tank Flange

- Enhanced trim & inspection prior to
- Performed thermal/vac tests for ΛP void time-to-divot (used in PRA)

Bipod Fitting Closeout

- Sealed/filled bipod wires to mitigate cryoingestion
- Enhanced / validated harness bonding process to eliminate void volume under harnesses
- Test verified
- Eliminated LO2 and LH2 PAL







2.0 Resolution of Anomalies from Previous Flight – Mitigations for STS-121

- PAL ramp and bipod closeout TPS loss mitigated through redesign
 - PAL ramp elimination design certified and application of TPS verified
 - Sufficient data provided by wind tunnel, CFD analysis and flight instrumentation to mitigate aero elastic concerns
 - Bipod harness seal/fill was test demonstrated to reduce cryo-ingestion leak path
 - Mitigation demonstrated through qualification test and process demonstration
- Thrust strut flange loss and ice/frost ramp loss at Xt 1525 most probably caused by external (secondary) impact, requiring no mitigation
 - Additional test data generated to validate void distribution
- Most probable cause for delta P divot events observed for Intertank flange closeout, LH2 acreage at Xt 1163 and ice/frost ramp body at Xt 1262, later than ASTT = 166 sec
 - Test-based analysis used to assess risk of delta-P voids, including additional data to verify time of release (input to Probabilistic Risk Assessment)
 - ET-120 LH2 ice/frost dissection data increased the population of the void data base
 - PRA performed based on 'debris cloud' including all failure mechanisms





Page 8

Presenter **Resolution of Anomalies from** 2.0 M. Quiggle, LM-ET/ 3000 **Previous Flight – Mitigations for STS-121** Date June 16, 2006

- Acreage loss at Xt 1851 most probable cause identified as cryopumping divoting due to
 - subsurface delaminations observed under acreage foam ice/frost ramp body
 - Ice/frost ramp certification testing (due to PAL ramp elimination) used to demonstrate performance for TPS debris requirements - Complete
 - Wind Tunnel Tests demonstrated ascent critical environment using full scale ice/frost ramp (max design dynamic pressure)
 - Cryo/thermal vac tests used to demonstrate prelaunch/ascent critical environments (max environments)
 - Stress analysis provided understanding of TPS cracks / delaminations
 - Flat panel flaw tolerance thermal/vac test validated stress analysis
- Flight history assessment supports analysis that TPS debris is not expected to exceed values identified and used for input to the PRA

Root Cause of STS-114 In-Flight Anomalies Identified - IFAs closed through ET Project CCB



STS-121

SPACE SHUTTLE PROGRAM Shuttle Propulsion NASA Marshall Space Flight Center, Huntsville, Al

4.1 Requirements Changes Since Previous Flight

Presenter M. Quiggle, LM-ET/ 3000

June 16, 2006


Date

Page 9

Change Description	SSP Requirement	ET Requirement (End Item Specification)				
Launch Probability	Launch Probability					
Extended 'no-ice' zone and PAL elimination impact	 NSTS 07700, Vol. X, Book 1, Para 3.2.1.2.14.1 - Approved Launch Holds due to ice formation shall not occur more than 11% of the time on an annual basis based on atmospheric conditions at the launch pad in the proximity of applicable launch vehicle Exception for No-PAL ramp retrofit tanks (15%) 	EIS Para 3.2.1.6.1 – Approved				
ET Debris Requirements						
Potential Change - Extension of 'no-ice' zone from 100° to 110° of +Z	NSTS 08303 Ice/Debris Inspection Criteria Update • Levied by NSTS 16007, Launch Commit Criteria, ICE-01 • CR S063412 released for review 6/12	EIS Para 3.2.1.6.1, 3.2.1.1.17 and 3.2.1.6.4 – No expected impacts				
Update TPS certification limitations	NSTS 60555, Verification Limitations for the External Tank Thermal Protection System • CR S062571A reviewed at PRCB 6/8/06, pending approval	EIS Para 3.2.1.1.17 and 3.2.1.6.6 • Pending CR approval • No issues				
Update debris allowables to ensure consistent SSP and ET Project debris requirements	 NSTS 60559, Expected Debris Generation and Impact Tolerance Requirements, Groundrules and Assumptions – Pending Approval CR S063369 reviewed at SICB 06/06/06 – Approval deferred to PRCB 	EIS Para 3.2.1.1.17 and 3.2.1.6.6 • Pending CR approval • No issues				
Induced Environment Updates						
Thermal Environments Vehicle Loads, and Protuberance Airloads Used for Hardware Design	 NSTS 07700, Vol. X, Book 2, Appendix 10.11 – Pending formal transmittal and incorporation into Appendix 10.11 "CDR" environments transmitted to ET via SSP web site CR S063281 reviewed at SICB 6/13/06 – Pending 	EIS para 3.2.7.1 • Pending CR approval • No issues				







SPACE SHUTTLE PROGRAM

Shuttle Propulsion NASA Marshall Space Flight Center, Huntsville, AI



STS-121

Configuration Changes Since Previous Flight Presenter 4.2 Date

M. Quiggle, LM-ET/ 3000 Page 11

June 16, 2006

Change Description	Reason for Change	Basis for Certification	Verification Status	
 Sealed/filled bipod wires Enhanced / validated harness bonding process 	 Debris mitigation (IFA corrective action) Mitigate cryoingestion leak path and eliminate void volume 	 Test Demonstration 	\checkmark	
Revised bipod fitting to tank fastener length from 0.875" to 1.0" (6 places ea fitting)	 Ensure adequate breakaway torque 	• Test • Analysis	\checkmark	
Replaced bipod strut lubricated washer with non- lubricated washer and dry-lube nut and revised torque requirements (12 plcs ea strut)	 Preclude excessive bolt elongation and preload 	 Test Analysis Bipod Struts 	√ Yoke to	
Regult at junction where Kapion is the third at junction where Kapion is the that mess bearing that the third at junction where Kapion is the that have that have that have that have the that have th				





4.2 Configuration Changes Since Previous Flight

Presenter M. Quiggle, LM-ET/ 3000

Date

June 16, 2006

Page 12	

Change Description	Reason for Change	Basis for Certification	Verification Status
Sanded / vented additional Intertank acreage TPS similar to other Intertank acreage	 Debris mitigation Reduce TPS thickness / potential debris size 	• Test • Analysis	\checkmark
Install development flight instrumentation (DFI) suite to obtain accelerometer data from accelerometers in LO2 cable tray (4) and LH2 cable tray (8)		• Test • Analysis	\checkmark
 Eliminated LO2 and LH2 PAL ramps Re-sprayed foam over acreage / adhesive in removal footprint, as required Modified ice/frost ramps, cable tray fairing, supports as required 	 Debris mitigation (IFA corrective action) Reduce potential TPS debris Ice/Frost Ramp Extensions 	 Inspection Test Analysis Demonstration Development Flight Instrumentation Intertank acreage Sanded/vented areas	



STS-121

7.0 STS-121 Readiness Assessment

Presenter M. Quiggle, LM-ET/ 3000

June 16, 2006

Page 13

Category	Topics	STS-121/ET-119 Rationale/ Mitigation	Status
Flight Anomalies from Previous Flight	 Bipod closeout loss (Redesign) LH2 PAL ramp loss (Redesign) Intertank flange loss (Reqmt update) Ice/frost ramp losses (Reqmt update) LH2 acreage loss (Reqmt update) Thrust strut flange loss (Reqmt update) 	Root cause identified – Required corrective actions implemented	G
Configuration Changes	 Bipod harness revisions Bipod fitting bolt length Bipod strut bolt revisions Development Flight Instrumentation Intertank acreage TPS venting / sanding PAL ramp elimination 	Design implemented, verified and certified – No issues	G
Requirements Changes	TPS debris requirementsInduced environment updates	Received environments assessed – No issues	G
Limited Life Component Status	Age and cycle sensitive hardware	All items within required life	G



STS-121

Page 14

7.0 STS-121 Readiness Assessment

SPACE SHUTTLE PROGRAM Shuttle Propulsion NASA Marshall Space Flight Center, Huntsville, Al

Presenter M. Quiggle, LM-ET/ 3000

June 16, 2006

Item	Topics	STS-121/ET-119 Rationale/ Mitigation	Status
Senior Management Review Items	 Conathane requalification GO2 vent duct breakthrough Ice/frost ramp application 	Dispositioned – No issues • Use as is • Repaired • No defect	G
Launch Site Processing	 Out of position processing PR/MRB Dispositions Planned Work Changes OMRSD Changes LCC Changes Software Changes Facility Changes 	 Complete - No issues Dispositioned - No issues Approved - No issues Approved - No issues Approved - No issues Approved - No issues Assessed - No issues (validation complete) Assessed - Potential impact to LCC due to facility ground valve change 	G
Acute Launch Emergency Reliability Tip (ALERT)	Applicable items	No issues	G
	Design Certification Review RIDs	Closed – No issues	G
Certification	Certificate(s) of Qualification (COQ)	Complete – No issues	G
Status	Hardware Certification Sheets (HCS)	Complete – No issues (2 remaining open shown as CoFR Exception)	G
	Exception / Waiver / Deviation Status	All approved – No issues	G



STS-121

Page 15

7.0 STS-121 Readiness Assessment

Presenter M. Quiggle, LM-ET/ 3000

June 16, 2006

Item	Topics	STS-121/ET-119 Rationale/ Mitigation	Status
	ECO sensor #2 resistance shift	ECO sensors removed / replaced with sensors subjected to Nanofocus x-ray	G
	Propulsion Line Hardware Safe Life Analysis	• Mission > 4	G
	LO2 tank pressure decay	GO2 vent valve removed / replaced	G
Technical Assessments	NESC concern for ET-119 Bipod fitting bolt insert locking feature	 Tests indicate that main contributors to loss of insert locking feature are high preload and minimum thread engagement Bipod bolt thread increased by 0.125 in. to potentially preclude loss of insert locking feature Reviewed at SERB – ET-119 cleared 	G
	Acceptability of thick TPS applications	 Tests and analysis demonstrated that TPS cracks do not lead to delaminations except for LH2 IFRs Tests and analysis demonstrate LH2 IFRs performance for TPS debris requirements 	G
	 MLP prepress ground valve cycle timing Potential LCC violation (and inadvertent scrub) due to new ground valve for LH2 prepressurization 	 Proposed resolution presented at 6/10 ICB No actions currently planned for STS-121 Pending final review by PRCB 6/15 	Y Pending SSP disposition



SPACE SHUTTLE PROGRAM Shuttle Propulsion NASA Marshall Space Flight Center, Huntsville, AI



	7.0 STS-121 Readiness A	ssessment	Presenter M. Quiggle, I	_M-ET/ 3000
	Open Work		Date June 16, 2006	Page 16
Item	Open Item	STS-121/ET-119 Ratio	nale/ Mitigation	Status
SSP Requirements• Updates to Design Requirements pending• ET-119 design asses changes• NSTS 60555 update (S06271A) • NSTS 60559 update (S063369) • NSTS 60559 update (S063411) • Induced environments updates (S063281)• ET-119 design asses changes		ssed against	Y Pending PRCB approval	
Certification Status	 HCS S506, LH2 Cable Tray and Pressurization Line Support Installation HCS S514, LH2 C/T Segments, Covers & Rubber Dams 	 Design verification of Final signatures per No issues 	•	Y CoFR Exception
FMEA/CIL	Updates due to Vol. V, TPS due to Bipod revisions PAL elimination, environment updates and ET-120 dissection results (ice/frost ramps)	 CIL retention rational approved by Level II CRs S040221V and S PRCB OSB approval No issues 	I 5040221Y pending	Y CoFR Exception
Hazard Analysis Reports	 • Updates due bipod changes, PAL elimination, environment updates and ET-120 dissection results (ice/frost ramps) 	 Hazards risk ranking Level III CRs S050411AQ, S050411AU pend approval No issues 	S050411AT,	Y CoFR Exception

No issues

CR S0050411AV pending PRCB disposition / approval, ECD 6/15





7.0 STS-121 Readiness Statement


Page 17

The External Tank, ET-119, is ready for STS-121 launch pending completion/closure of open and planned work

Michael Quiggle, ET Project Chief Engineer Lockheed Martin Space Systems Company, Michoud

Wanda Sigur, ET Project Manager Lockheed Martin Space Systems Company, Michoud Kenneth Welzyn, Chief Engineer External Tank Marshall Space Flight Center, NASA

John Chapman, Manager External Tank Marshall Space Flight Center, NASA






STS-121

Page 19

Presenter W. Sigur, LM/ET-3000 **Special Topic – Possible Outcomes** 8.1 Specific Possible Foam Losses for ET 119/STS-121 Date June 16, 2006

- ET119 NDE Inspections
 - TPS NDE was performed on ET119 based on accessibility of NDE tooling
 - Ice Frost Ramp inspections completed via BSX (backscatter) & THz (terahertz)
 - Surrounding acreage inspected via Shearography
 - LO2 Stations: 760, 794, 828
 - Intertank Stations: 861, 897, 922, 949
 - LH2 Stations: 1151 through 1851
 - BX Extensions (all stations)
 - LO2 & LH2 PAL Ramp footprint inspections completed via Shearography
- Worst case assessment
 - Force a divot, and
 - Create largest mass








8.1 Special Topic – Possible Outcomes Possible Foam Losses for ET 119/STS-121 Based on NDE

Presenter W. Sigur, LM/ET-3000

June 16, 2006

Date

Page **20**



Station 828: Small cluster of porosity in extension spray.

Area of cluster = 1.25" dia


Mass = 0.017 lbm

NSTS 60559: 0.026 = Risk Assessment Mass

Notes: Geometric defect, tied to bracket also observed at STA 794. (No divot expected due to depth) "Unexpected divot" max mass = 0.011 lbm






















Station 1787: Small cluster of porosity in PDL flow lines

Area of cluster = 0.5" dia

Mass = 0.011 lbm

NSTS 60559: 0.084 = Risk Assessment Mass Station 1722: Two void locations

Area = 0.3" dia and 0.4" dia

Mass = 0.003; 0.003 lbm, resp

NSTS 60559: 0.084 Ibm = Risk Assessment Station 1528: Flow lines with a void

Area = 1.0" dia

Mass = 0.008lbm

NSTS 60559: 0.084 Ibm= Risk Assessment Mass

Note: Geometric defects, tied to bracket observed set STA 1399, 1528, and 1851. (no divot due to depth) "Unexpected divot" max mass = 0.011 lbm




STS-121

8.1Special Topic – Possible Outcomes
Possible Foam Losses for ET 119/STS-121 Based on NDEPresenterW. Sigur, LM/ET-3000Date
June 16, 2006

- NDE using shearography identified potential risk for crushed foam losses
 - Crushed foam indications noted at stations 1151, 1205, 1528, 1593, 1722 and 1787
 - Visual inspections also performed in area to assess risk
 - Visual methods validated by test
 - Typical scans noted





STA 1787

STA 1722

STA 1593

STA 1528





Page 24

8.2 Special Topic LON Readiness Assessment

- ET-118 designated for LON requirements
- Assessment of ET-118 to support STS-114 LON
 - No significant issues identified
 - Closure/mitigation plans in place to support required LON processing and CoFR milestones





STS-121 Flight Readiness Review

External Tank Project (ET-119)

Back-Ups



June 16, 2006




SPACE SHUTTLE PROGRAM Shuttle Propulsion NASA Marshall Space Flight Center, Huntsville, Al



Induced Environment Update Assessment

Presenter M. Quiggle, LM-ET/ 3000
Date June 16, 2006 Page BU-2

- Environment Impacts
 - New environments received from SE&I and assessed for impacts to structure
 - Updates to existing thermal and steady airloads environments
 - New unsteady airloads environment
 - Environment updates result from
 - PAL ramp elimination
 - New methodology used by SE&I
 - to generate environments
 - Resulting environments
 - cover entire tank
 - Environments provided for the
 - following protuberances
 - LO2 and LH2 cable trays
 - GO2 and GH2 presslines
 - LO2 feedline
 - Aft protuberance hardware with increases over existing Loads Data Book







Induced Environment Update Assessment

Presen	^{iter} M. Quiggle, Ll	M-ET/ 3000
Date	June 16, 2006	Page BU-3

- Verification of the revised requirements were performed by Analysis and Test
 - Analysis resulted showed adequate structural factor of safety for affected hardware
 - No additional testing required for factor of safety demonstration
 - Additional testing was required for safe life demonstration
 - Glass epoxy support brackets for LH2 and LO2 presslines and cable trays





Induced Environment Update Assessment

- Design Verification for Updated Environments
 - Analysis Adequate structural factor of safety for affected hardware
 - No additional testing required for factor of safety demonstration
 - Additional testing was required for safe life demonstration
 - Glass epoxy support brackets for LH2 and LO2 presslines and cable trays
 - Tests, Complete
 - LO2 tank cable tray support bracket bolt and fillet weld testing performed to provide additional confidence in analytical results
 - Tests complete and demonstrated capability > 200% DLL
 - LO2 and LH2 cable tray support glass epoxy simulated service
 - Two test articles each subjected to 4 mission cycles
 - "Barely visible' damage induced into test articles
 - Both test articles incurred no permanent deformations or flaws
 - The 'barely visible' damage had no noticeable changes
 - Test-demonstrated capability >200% DLL following mission life testing



LO2 Cable Tray Support Simulated Service Test





LH2 Ice/Frost Ramp Flight Rationale

- Issue
 - Concern for risk of LH2 ice/frost ramp process defects and thermally-induced cracks / delaminations resulting in unacceptable debris
- Background
 - STS-114 Foam Loss Events Root Cause Investigation Summary
 - PAL ramp and bipod closeout TPS loss mitigated through redesign
 - Thrust strut flange loss and ice/frost ramp loss (Xt 1525) most probably caused by external (secondary) impact
 - Delta P divot events observed for Intertank flange closeout, LH2 acreage (Xt 1163) and ice/frost ramp body (Xt 1262 and Xt 1841) assessed through SSP PRA
 - Ice/frost ramp (IFR) losses > max expected performance based on pre STS-114 process assessment for void characterization
 - Dissection of mock-ups and ET-120 IFRs confirmed larger than expected voids in IFR body
 - Revised process assessment data used to update probabilistic risk assessment assumptions

Debris Source	Failure Modes	Model Input	RCC Risk	Tile Risk	Special Tile Risk
	Void DP	ET Debris Table	1/10,000	1/110	1/250
LH2 IFR &	Cryo-Pumping	MSFC Flt History	1/7,000	1/5,000	n/c
Adjacent Acreage	Thermal Cracks	MSFC Flt History	1/1,000	1/75-1/125	n/c
	Airloads	MSFC Flt History	No risk	1/750	n/c







LH2 Ice/Frost Ramp Flight Rationale



- Background (cont.)
 - STS-114 Foam Loss Events Root Cause Investigation Summary
 - Acreage loss at Xt 1851 most probable cause identified as cryopumping divoting due to subsurface delaminations
 - Observed under acreage foam LH2 ice/frost ramp body on ET-120 'typical' IFR configurations (after 2 cryo / pressurization cycles)
 - Delaminations not observed under Xt 1334 IFR
 - Different configuration than typical LH2 IFR configurations
 - Damage mostly in NCFI within IFR footprint; although some PDL damage (IFR body)










LH2 Ice/Frost Ramp Flight Rationale

- TPS Cracking (Delamination) Root Cause Assessment
 - Component test and analysis shows that cracks and delaminations correspond to high thermally-induced loading and stress risers resulting from dissimilar TPS stiffness and geometric stress risers at cryogenic temperatures
 - Part by part assessment showed cracks at these locations
 - LH2 ice/frost ramps
 - Bipod
 - Intertank / LH2 tank flange
 - Intertank acreage valleys
 - Vertical struts
 - Delaminations only observed at LH2 ice/ frost ramp locations
 - All TPS applications were assessed to determine susceptibility to TPS crack-induced failures during ASTT (< 166 sec MET)
 - Tests and analysis demonstrated that TPS cracks do not lead to delaminations except for LH2 ice/frost ramps
 - Crack / delams can contribute to cryopumping, delta pressure, or aeroshear debris
 - Subsurface delaminations are possible for large, thick TPS applications at cryogenic temperature and exposed to high substrate mechanical strains
 - Acreage TPS susceptible but not considered a 'high risk'
 - Previous testing performed and demonstrates adequate capability (SF = 1.25)

Test And Analysis Show Subsurface Delaminations Not Expected Except At LH2 IFR Locations

Dissection / Analysis Correlation



Presenter	M. Quiggle, LM	I-ET/ 3000
^{Date} Ju	ne 16, 2006	Page BU-7








Page BU-8


LH2 Ice/Frost Ramp Flight Rationale

June 16, 2006

- STS-121/ET-119 Flight Rationale
 - Foam loss due to multiple environments assessed
 - Aeroshear (Debris not expected)
 - AEDC wind tunnel testing demonstrated that cracks without visible off-set a crack face are acceptable (i.e. no debris)
 - Cryopumping (Debris expected)
 - Cryopumping-driven divoting during ASTT (<166 sec) possible for areas highlighted (incl. bipod, flange, LO2 feedline closeout and LH2 acreage and IFRs)
 - Delams only observed / expected at LH2 IFR locations
 - Low probability of critical debris at critical time based on DTA assessment (1/5,000)
- Area susceptible to cryopumping divoting during ASTT (<166s)



- Delta Pressure (Debris not expected)
 - Thermodynamics/fracture based analysis and testing performed for LH2 IFR TPS shows delta pressure loading not sufficient to cause delam crack growth during ASTT (1/75 assuming loss at critical time)
 - Cryo/Thermal Vac tests performed to characterize debris potential and failure mechanisms subjected to cryo cycling and simulated launch conditions
 - No observed debris liberated



Thermal Vac Test Article Configuration





LH2 Ice/Frost Ramp Flight Rationale

- STS-121/ET-119 Flight Rationale Summary (TPS Cracks / Delaminations)
 - Ice/frost ramp certification testing (due to PAL ramp elimination) used to demonstrate performance for TPS debris requirements Complete
 - Wind Tunnel Tests used demonstrated ascent critical environment using full scale ice/frost ramp (max design dynamic pressure)
 - Cryo/thermal vac tests used to demonstrate prelaunch/ascent critical environments
 - Full scale ice/frost ramp (max environments)
 - Test articles subjected to cryo and ascent thermal/vacuum profiles
 - Stress analysis provides understanding of TPS cracks / delaminations
 - Flat panel flaw tolerance thermal/vac test validate stress analysis
 - Panels include engineered flaws
 - Subjected to cryo and ascent thermal/vac profiles
 - ET-120 LH2 ice/frost dissection data increase the population of the void data base
 - PRA performed based on 'debris cloud' including all failure mechanisms
 - Limitations associated with design verification (with crack / delaminations) recognized/documented by SSP
 - TPS inspected during Prelaunch to determine that identified cracks meet acceptance criteria in the Launch Commit Criteria, ICE-01 (i.e. no off-sets at crack face)
 - Acceptance criteria based on tests, analysis and demonstration
 - Flight history assessment supports analysis that TPS debris is not expected to exceed values identified and used for input to the PRA